

Affected Dispatch Interval Report

Trading Month July 2026

Prepared in accordance with
clause 7.11C.3 of the ESM Rules





1 Introduction

The Australian Energy Market Operator (AEMO) has prepared this report under clause 7.11C.3 of the Electricity System and Market Rules (ESM Rules).

Clause 7.11C.3 of the WEM Rules requires AEMO to publish a report as soon as practicable after determining a Dispatch Interval is an Affected Dispatch Interval outlining:

- the reasons for determining that a Dispatch Interval was an Affected Dispatch Interval.
- whether that determination was correct; and
- what action will be taken to minimise the risk of a similar event in future.

In this report:

- the reporting period covers the period specified on the title page,
- terms that are capitalised but not defined have the meaning given in the WEM Rules; and,
- date references are to Trading Days, not calendar days, unless otherwise stated.

Affected Dispatch Interval(s)

This section provides details of the Dispatch Intervals AEMO has determined to be Affected Dispatch Intervals in accordance with 7.11C.2. In accordance with clause 7.11C.3(b) at the time of publication of this report AEMO considers the determination correct.

Trading Day	10 July 2026	
Dispatch Interval(s)	Affected Dispatch Interval	Replacement Market Schedule Run
	2026-07-10 16:25	2026-07-10 16:20
	2026-07-11 06:20	2026-07-11 06:15
Reasons for Determination [7.11C.3(a)]	The SCADA tags reflecting the ramp rate setpoints of a single Facility erroneously zeroed. In accordance with Clause 7.11B.1B (a) of the ESM Rules, AEMO replaced the Affected Dispatch Intervals with the forecasted Dispatch Intervals from the most recent Dispatch Schedule AEMO reasonably considered to not include manifestly incorrect data. AEMO has determined that these intervals are Affected Dispatch Intervals as the market outcomes were based on manifestly incorrect information, directly resulting in material impacts to Market Clearing Prices.	
Determination Outcome [7.11C.3(b)]	Correct	
Actions Taken [7.11C.3(c)]	AEMO re-issued the desired ramp rate setpoint, rectifying the issue.	